

North America Emission Control Area Fuel Oil Non-Availability Report

ECA0100

1

2

3

##

##(Include Double Pound for comments, not form fields)

##Report Form ID

Ship Operator Name

Vessel Name

Clipper Steel Services LTD Clipper Valour

4

5

6

7

8

Flag Country	IMO ID Number	Date of ECA First Notice	Location of ECA First Notice	Name of Ports after First Notice
BS	9285407	2/13/2015	Piacaguera, Brazil	Praia Mole & Itaguai, Brazil

Name of Last Port before ECA Entry	Name of Port with Fuel Oil Supply Disruption
Itaguaí, Brazil	Piacaguera, Praia Mole & Itaguaí, Brazil

11

12

13

Name of Original Fuel Supplier with Disruption	Number of Fuel Suppliers Contacted	Date of Entry in the ECA
PETROBRAS	PETROBRAS	3/16/2015

4

14

15

16

Time of Entry in the ECA	Sulfur Content of Non-Compliant Fuel Oil	Projected Hours on Main Propulsion
1200	0.9	24

17

18

19

Name of First POC	Compliance Fuel Oil Available at First POC?	Plan to Bunker Compliant Fuel Oil at First POC?
Philadelphia, PA	Y	Y

20

21

22

Number of fuel suppliers contacted at First POC	Name of Second POC	Compliant Fuel Oil at Second POC?
NA	NA	NA

Plan to Bunker Compliance Fuel Oil at Second POC?
NA

Number of Fuel Suppliers Contacted at the Second POC?
NA

25

26

27

Date of Exit from ECA?	Time of Exit from ECA?	Has this vessel operated in the ECA in previous 12 months?
3/23/2015	1200 Y	

28

29

30

Number of Separate Visits to the ECA	Number of Ports visited in the ECA	Previously submitted ECA0100 forms?
1	2	Y

Number of Submitted Reports	Designated Corporate Official Name	Designated Corporate Official E-mail
2	Mr. Ronald Coote	bulk.steel@clipper-group.com

Designated Corporate Official Phone Number	Description of Actions to Achieve Compliance
7139532247	Took delivery of vessel in Brazil